

April 25, 2005

Mr. Bob Anderson  
State of Utah DFCM  
4110 State Office Bldg  
Salt Lake City, UT 84114

Ref: Batch #65219, Lab #DFC1035-DFC1036  
Received April 22, 2005  
Test Report  
Hazardous Materials Program  
Analytical Air & Bulk Testing Services  
DFCM Proj #03164310/ Contract #037527  
UNG Armory - Logan, UT  
Sampled by Bob Anderson, 4/22/05

Dear Mr. Anderson:

Samples DFC1035 through DFC1036 have been analyzed by visual estimation based on EPA-600/M4-82-020 December 1982 optical microscopy test method. Appendix "A" contains statements which an accredited laboratory must make to meet the requirements of accrediting agencies. It also contains additional information about the method of analysis. Appendix "A" must be included as an essential part of this test report.

This report may be reproduced but all reproduction must be in full unless written approval is received from the laboratory for partial reproduction. The results of analysis are as follows:

Lab DFC1035, Field 001 09:00 - ARM, Flashing material

This sample contains five types of material: The first type is silver colored sealant; the second type is 20% fiberglass in black tar layers; the third type is black tar layers; the fourth type is 50% plant fiber in black tar felt; the fifth type is brown wood fiber. This sample is non-homogeneous. **Asbestos is none detected.**

The first type is 2% of the sample. The second type is 38% of the sample. The third type is 40% of the sample. The fourth type is 10% of the sample. The fifth type is 10% of the sample.

Lab DFC1036, Field 002 09:20 - ARM, Roof material

This sample contains three types of material: The first type is 20% fiberglass in black tar layers; the second type is black tar layers; the third type is perlite and 40% wood fiber. This sample is non-homogeneous. **Asbestos is none detected.**

The first type is 35% of the sample. The second type is 55% of the

Batch #65219  
Lab #DFC1035-DFC1036  
Page 2 of 2

sample. The third type is 10% of the sample.

In order to be sure reagents and tools used for analysis are not contaminated with asbestos, blanks are tested. Asbestos was none detected in the blanks tested with this bulk sample set.

Very truly yours,

Steve H. Dixon, President

Analyst: Steve Dixon \_\_\_\_\_ Date Analyzed: 4/22/05